

S1003/0077

cc: Lynn

Task: 4718

RECEIVED

FEB 29 2012

DIV. OF OIL, GAS & MINING

Form MR-REV-SMO (DOGM – Revise/Amend Change Form)
(Revised November 21, 2006)

Application to Revise a Notice of Intention to Commence Small Mining Operations or Exploration

Operator: Century Gold Mining and Milling Company, Inc.

Mine Name:

Century

File Number: E or M/

S1003/0077

Provide a detailed listing of all changes to the Notice that will be required as a result of this change. Individually list all maps and drawings that are to be added, replaced, or removed from the Notice. Include page, section and drawing numbers as part of the description.

DETAILED SCHEDULE OF CHANGES TO THE NOTICE

			Description of map, text, or materials to be changed
ADD	REPLACE	REMOVE	NOI Page 5 Level II adit
ADD	REPLACE	REMOVE	NOI Page 5 Mill level pond + ore pad
ADD	REPLACE	REMOVE	NOI Page 5 New road to level III
ADD	REPLACE	REMOVE	NOI Page 5 Level III blocked out testing ore
ADD	REPLACE	REMOVE	
ADD	REPLACE	REMOVE	*Total disturbed acres proposed and past is three acres.
ADD	REPLACE	REMOVE	
ADD	REPLACE	REMOVE	
ADD	REPLACE	REMOVE	

I hereby certify that I am a responsible official of the applicant and that the information contained in this application is true and correct to the best of my information and belief in all respects with the laws of Utah in reference to commitments and obligations, herein.

Gary Gillespie

Print Name

Gary Gillespie, President

Sign Name, Position

27 Feb 2012

Date

Return to:

State of Utah
Division of Oil, Gas and Mining
Attn: Minerals Regulatory Program
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Phone: (801) 538-5291 Fax: (801) 359-3940
P:\GROUPSW\MINERALS\WP\FORMS\Notices\Final\revision_SMO_EXP.doc

FOR DOGM USE ONLY:
File #: M/ /
Approved: _____
Bond Adjustment: from \$ _____
to \$ _____

5. Provide a brief description of the proposed mining operation and onsite processing facilities (add extra pages if necessary). Century site - level II adit open old adit workings which occasionally discharge water (spring time), secure with 2-6' diameter x 20' corrugated steel drain pipe and appropriate steel locked gate. This adit should not be backfilled as we intend to explore and develop if assay warrant allows to be used for storage

6. New Road(s): Length _____ (ft) Width _____ (ft)

7. Improved Road(s): Provide a description of the improvements that need to be made to existing roads to access the site, including the Length _____ (ft) and Width _____ (ft) of new disturbances.

8. Total project surface acreage to be disturbed: Two (acres) PLEASE SPECIFY EXACT ACREAGE - (this will be used to determine surety bond amount - see #VI).

9. Proposed startup date (month, year) _____
10. Proposed completion date, if known (month, year) _____

IV. OPERATION AND RECLAMATION PRACTICES (Rule R647-3-107, 108 & 109)

The reclamation and operation obligation is to keep the area clean and safe, minimize hazards to public safety, return the land to a useful condition, and reestablish at least 70 percent of the premining vegetative ground cover or within practical limits. To accomplish this, the Permittee / Operator will need to perform reclamation concurrently, or at the completion (within one (1) year) of mining. Please refer to The Practical Guide to Reclamation in Utah, available at https://fs.ogm.utah.gov/pub/MINES/Coal_Related/RecMan/Reclamation_Manual.pdf.

1. Keep the mining operation in a safe, clean, and environmentally stable condition.
2. Permanently seal all shafts and tunnels to prevent unauthorized or accidental entry.
3. Plug drill holes with a five foot cement surface plug. Holes that encounter fluids are to be plugged in the subsurface to prevent aquifer contamination.
4. Construct berms, fences, or barriers, when needed, above highwalls and excavations.
5. Remove, isolate, or neutralize all toxic materials in a manner compatible with federal and state regulations.
6. Remove all waste or debris from stream channels.
7. Dispose of any trash, scrap metal, wood, machinery, and buildings.
8. Conduct mining activities so as to minimize erosion and control sediment.
9. Reclaim all roads that are not part of a permanent transportation system.
10. Stockpile topsoil and suitable overburden prior to mining.

b.

5. Provide a brief description of the proposed mining operation and onsite processing facilities (add extra pages if necessary). Century Site Mill level Pond + ore pad. Build 10 ft deep, 50 ft x 40 ft oval, concave pond on top of existing dump. To be filled by water draining from spring with overflow draining out to same area as before. Build a 6 ft high fence around the pond to keep animals out. Pond lined with plastic liner. Ore pad/process area 40 ft x 70 ft adjacent to pond on existing dump.

6. New Road(s): Length _____ (ft) Width _____ (ft)

7. Improved Road(s): Provide a description of the improvements that need to be made to existing roads to access the site, including the Length _____ (ft) and Width _____ (ft) of new disturbances.

8. Total project surface acreage to be disturbed: Two (acres) PLEASE SPECIFY EXACT ACREAGE - (this will be used to determine surety bond amount - see #VI).

9. Proposed startup date (month, year) _____

10. Proposed completion date, if known (month, year) _____

Previously Bonded

IV. OPERATION AND RECLAMATION PRACTICES (Rule R647-3-107, 108 & 109)

The reclamation and operation obligation is to keep the area clean and safe, minimize hazards to public safety, return the land to a useful condition, and reestablish at least 70 percent of the premining vegetative ground cover or within practical limits. To accomplish this, the Permittee / Operator will need to perform reclamation concurrently, or at the completion (within one (1) year) of mining. Please refer to The Practical Guide to Reclamation in Utah, available at https://ts.ogm.utah.gov/pub/MINES/Coal_Related/RecMan/Reclamation_Manual.pdf.

1. Keep the mining operation in a safe, clean, and environmentally stable condition.
2. Permanently seal all shafts and tunnels to prevent unauthorized or accidental entry.
3. Plug drill holes with a five foot cement surface plug. Holes that encounter fluids are to be plugged in the subsurface to prevent aquifer contamination.
4. Construct berms, fences, or barriers, when needed, above highwalls and excavations.
5. Remove, isolate, or neutralize all toxic materials in a manner compatible with federal and state regulations.
6. Remove all waste or debris from stream channels.
7. Dispose of any trash, scrap metal, wood, machinery, and buildings.
8. Conduct mining activities so as to minimize erosion and control sediment.
9. Reclaim all roads that are not part of a permanent transportation system.
10. Stockpile topsoil and suitable overburden prior to mining.

5. Provide a brief description of the proposed mining operation and onsite processing facilities (add extra pages if necessary). Century Mine New Road to level III
-
-
-

6. New Road(s): Length 2000 (ft) Width 16 (ft)

7. Improved Road(s): Provide a description of the improvements that need to be made to existing roads to access the site, including the Length _____ (ft) and Width _____ (ft) of new disturbances.

8. Total project surface acreage to be disturbed: 0.72 (acres) PLEASE SPECIFY EXACT ACREAGE - (this will be used to determine surety bond amount - see #VI).

9. Proposed startup date (month, year) _____
10. Proposed completion date, if known (month, year) _____

IV. OPERATION AND RECLAMATION PRACTICES (Rule R647-3-107, 108 & 109)

The reclamation and operation obligation is to keep the area clean and safe, minimize hazards to public safety, return the land to a useful condition, and reestablish at least 70 percent of the premining vegetative ground cover or within practical limits. To accomplish this, the Permittee / Operator will need to perform reclamation concurrently, or at the completion (within one (1) year) of mining. Please refer to The Practical Guide to Reclamation in Utah, available at https://fs.ogm.utah.gov/pub/MINES/Coal_Related/RecMan/Reclamation_Manual.pdf.

1. Keep the mining operation in a safe, clean, and environmentally stable condition.
2. Permanently seal all shafts and tunnels to prevent unauthorized or accidental entry.
3. Plug drill holes with a five foot cement surface plug. Holes that encounter fluids are to be plugged in the subsurface to prevent aquifer contamination.
4. Construct berms, fences, or barriers, when needed, above highwalls and excavations.
5. Remove, isolate, or neutralize all toxic materials in a manner compatible with federal and state regulations.
6. Remove all waste or debris from stream channels.
7. Dispose of any trash, scrap metal, wood, machinery, and buildings.
8. Conduct mining activities so as to minimize erosion and control sediment.
9. Reclaim all roads that are not part of a permanent transportation system.
10. Stockpile topsoil and suitable overburden prior to mining.

5. Provide a brief description of the proposed mining operation and onsite processing facilities (add extra pages if necessary). Century level III blocked out testing ore.
5000 tons blocked out to collect for "Gravity" testing.

6. New Road(s): Length _____ (ft) Width _____ (ft)

7. Improved Road(s): Provide a description of the improvements that need to be made to existing roads to access the site, including the Length _____ (ft) and Width _____ (ft) of new disturbances.

8. Total project surface acreage to be disturbed: 0.13 (acres) PLEASE SPECIFY EXACT ACREAGE - (this will be used to determine surety bond amount - see #VI).

9. Proposed startup date (month, year) May 2012
10. Proposed completion date, if known (month, year) _____

IV. OPERATION AND RECLAMATION PRACTICES (Rule R647-3-107, 108 & 109)

The reclamation and operation obligation is to keep the area clean and safe, minimize hazards to public safety, return the land to a useful condition, and reestablish at least 70 percent of the premining vegetative ground cover or within practical limits. To accomplish this, the Permittee / Operator will need to perform reclamation concurrently, or at the completion (within one (1) year) of mining. Please refer to The Practical Guide to Reclamation in Utah, available at https://fs.ogm.utah.gov/pub/MINES/Coal_Related/RecMan/Reclamation_Manual.pdf.

1. Keep the mining operation in a safe, clean, and environmentally stable condition.
2. Permanently seal all shafts and tunnels to prevent unauthorized or accidental entry.
3. Plug drill holes with a five foot cement surface plug. Holes that encounter fluids are to be plugged in the subsurface to prevent aquifer contamination.
4. Construct berms, fences, or barriers, when needed, above highwalls and excavations.
5. Remove, isolate, or neutralize all toxic materials in a manner compatible with federal and state regulations.
6. Remove all waste or debris from stream channels.
7. Dispose of any trash, scrap metal, wood, machinery, and buildings.
8. Conduct mining activities so as to minimize erosion and control sediment.
9. Reclaim all roads that are not part of a permanent transportation system.
10. Stockpile topsoil and suitable overburden prior to mining.